

HRC弹性联轴器—尺寸与额定功率

TABLE:2 DIMENSIONS 表:2 尺寸

Taper-Lock						Bored to Size定规格孔径				DIA A	DIA B	DIA E	F	G	L ₁	L ₂	L ₃	J+
Size 规格	Bush 轴套	Bore 孔径		C	D	Bore 孔径#		C	D									
		Max 最小	Min 最大			Max 最小	Min 最大											
70	1008	25	9	19	23.5	32	8	21	25	69	60	31	27	18	65	66.5	68	29
90	1108	28	9	18.5	23.5	38	8	26	30	85	65	32	32.5	22.5	69.5	76	82.5	29
110	1610	42	14	18.5	26.5	55	8	37	45	112	100	45	45	29	82	101	119	38
130	1610	42	14	17.5	26.5	60	36	47	55	130	105	50	54	36	89	118	146	38
150	2012	50	14	23	33.5	65	40	50	60	150	115	62	61	40	107	134	160	42
180	2517	60	16	34	46.5	80	46	58	70	180	125	77	74	49	142	166	189	48
230	3020	75	25	39.5	52.5	100	52	77	90	225	155	99	85.5	59.5	165	202	240	55
280	3525	100	35	51	66.5	115	60	90	105	275	206	119	106	74.5	208	247	286	67

L₁ is the length with assembly combinations F.F.-H.H.F.F.H

L₁ is the length with assembly combinations F.B.-H.B

L₁ is the length with assembly combinations B.B

+ J is wrench clearance required for tightening and loosening the Bush on the shaft : the use of a shortened key will allow this dimension to be reduced.

≠ Bore limit H8 unless specified otherwise Dimensions in mm.

L₁是机组装配长度F.F.-H.H.F.F.H

L₂是机组装配长度F.B.-H.B

L₃是机组装配长度 B.B

+ J_s是松紧轴上轴套所需的扳手空间。

采用缩短了的扳手，可减少此一尺寸。

≠ 未注明的孔径极限为H8

尺寸以毫米为单位。

Fig.1 图：1

